

## **9. Why LC-01 is alarming?**

There is a specific alarm for protecting RF module. When it is alarming, please check:

- 1> The wire/cable connection and antenna installation; please make sure the wire/cable is connected well and properly;
- 2> The group of the antenna: especially the antenna is upgraded to higher grade (higher gain, like from omni to yagi), please check if the 'group' is corresponding to the base and remote unit; please check the serial number to make sure the group is correct.

If the above-mentioned problem is not found and corrected properly in time, the RF power will strike back to RF module and cause the damage of RF module (burnt) eventually.